


This map is a product of a BAER rapid assessment. Further information concerning the accuracy and appropriate uses of this data may be obtained from the USDA Forest Service. The Forest Service makes no warranty, expressed or implied, including the warranties of merchantability and fitness for a particular purpose, nor assumes any legal liability or responsibility for the accuracy, reliability, completeness or utility of these geospatial data, or for the improper or incorrect use of these geospatial data. These geospatial data and related maps or graphics are not legal documents and are not intended to be used as such. The data and maps may not be used to determine title, ownership, legal descriptions or boundaries, legal jurisdiction, or restrictions that may be in place on either public or private land. Natural hazards may or may not be depicted on the data and maps, and land users should exercise due caution. The data are dynamic and may change over time. The user is responsible to verify the limitations of the geospatial data and to use the data accordingly.



Soil Burn Severity

High soil burn severity:
All or nearly all of the pre-fire ground cover and surface organic matter (litter, duff, and fine roots) is generally consumed, and charring may be visible on larger roots. Soil is often gray, orange, or reddish at the ground surface where large fuels were concentrated and consumed.

Moderate soil burn severity:
Up to 80 percent of the pre-fire ground cover (litter and ground fuels) may be consumed but generally not all of it. There may be potential for recruitment of effective ground cover from scorched needles or leaves remaining in the canopy that will soon fall to the ground. Soil structure is generally unchanged.

Low soil burn severity:
The ground surface, including any exposed mineral soil, may appear (lightly charred), and the canopy and understory vegetation will likely appear "green."

Very Low or Unburned:
Little to no burn expected within these areas. Canopy and ground litter completely intact. Little to no vegetative mortality expected.

For additional information including photo examples of soil burn severity see the Field Guide for Mapping Post-Fire Soil Burn Severity at http://www.fs.fed.us/rm/pubs/mms_gf243.pdf

Burned Area Emergency Response

Terwilliger BAER

Willamette National Forest

Road Treatments

October 15, 2018

0 1/2 1

Miles

Road Hazard Sign

Storm Inspection and Response

Fire Perimeter - Sept. 28, 2018

National Forest Boundary

Other Land, Including Private

Road - Operational Maintenance Level

5 - High Degree of User Comfort

4 - Moderate Degree of User Comfort

3 - Suitable for Passenger Cars

2 - High Clearance Vehicles

1 - Basic Custodial Care (Closed)

Non FS Road